



Wiring Instructions for 1812-037 12 Volt DC 1.0A Power Transformer Assembly

Some power transformers may come supplied with a plug-in connector attached to the end of the supply line. If this is the case, remove the connector by cutting it off from the end of the supply wires.

This is a DC Transformer. Polarity must be observed!

The solid black wire is **POSITIVE**.

The wire with the white lettering is **NEGATIVE**.

